



Application Name: ShareLink
Current Version: 3.0.0.4

The following notes provide the revision history and a list of known software issues in the current release. For more information, please call your Extron Application Engineer.

Updated: July 7, 2020

Extron Products Affected:

Device	Minimum Firmware Version Required
ShareLink 200/250 Series	2.0.3.8

SPECIAL NOTES (If applicable)

TECH NOTES

Minimum System Requirements:

- Dual Core, 1.8 GHz processor or better
- Microsoft® Windows 7, 8, 10
- Graphics card with 64MB VRAM or better

Auto-discovery feature – The auto-discovery feature to detect available ShareLink receivers requires the PC and receiver to be connected to the same subnet.

Stream Video feature – Stream Video (video playback) feature requires the PC and receiver to be connected to the same subnet.

Pro version MSI Installer – The pro version of software exe installer is replaced with an MSI Installer.

Worldwide Sales Offices

Anaheim • Raleigh • Silicon Valley • Dallas • Chicago • New York • Washington, DC • Toronto • Mexico City • Paris • London • Frankfurt
 Amersfoort • Moscow • Dubai • Johannesburg • New Delhi • Bangalore • Singapore • Seoul • Shanghai • Beijing • Tokyo

UNITED STATES

+800.633.9876
 Inside USA/Canada
 +1.714.491.1500

EUROPE

+800.3987.6673
 Inside Europe
 +31.33.453.4040

ASIA

+800.7339.8766
 Inside Asia
 +65.6383.4400

MIDDLE EAST

+971.4.2991800



KNOWN ISSUES

The following is a list of known software issues found in the ShareLink Software Version 3.0.0.4

Issue (originated in v1.0.0.6) – Intermittent playback of Share Media (video playback) feature – The selected media file does not play. This is an intermittent issue. This can be resolved by either replaying the media or restarting the ShareLink software.

Worldwide Sales Offices

Anaheim • Raleigh • Silicon Valley • Dallas • Chicago • New York • Washington, DC • Toronto • Mexico City • Paris • London • Frankfurt
Amersfoort • Moscow • Dubai • Johannesburg • New Delhi • Bangalore • Singapore • Seoul • Shanghai • Beijing • Tokyo

UNITED STATES

+800.633.9876
Inside USA/Canada

+1.714.491.1500

EUROPE

+800.3987.6673
Inside Europe

+31.33.453.4040

ASIA

+800.7339.8766
Inside Asia

+65.6383.4400

MIDDLE EAST

+971.4.2991800



SOFTWARE RELEASE HISTORY

Released Version: 3.0.0.4**Affects:****Software Revision: 3.0.0.3****Date: July 7, 2020**

The following is a list of changes and fixes in this release.

Fixed Issue (originated in v3.0.0.3) – Incorrect passcode prompt when enabling “Allow control inputs from receivers” feature – When selecting “Allow control inputs from receivers” the user would be incorrectly prompted to enter a passcode. This issue has been resolved.

Improved Feature – General Housekeeping – General updates to software to improve stability and performance

Worldwide Sales Offices

Anaheim • Raleigh • Silicon Valley • Dallas • Chicago • New York • Washington, DC • Toronto • Mexico City • Paris • London • Frankfurt
Amersfoort • Moscow • Dubai • Johannesburg • New Delhi • Bangalore • Singapore • Seoul • Shanghai • Beijing • Tokyo

UNITED STATES

+800.633.9876
Inside USA/Canada

+1.714.491.1500

EUROPE

+800.3987.6673
Inside Europe

+31.33.453.4040

ASIA

+800.7339.8766
Inside Asia

+65.6383.4400

MIDDLE EAST

+971.4.2991800



SOFTWARE RELEASE HISTORY

Released Version: 3.0.0.3

Affects:

Software Revision: 2.0.1.4

Date: January 8, 2020

The following is a list of changes and fixes in this release.

Improved Feature – Updated software platform

Fixed Issue – Extended display not working in Windows 10 (originated in v2.0.1.4) – On certain windows 10 versions, the extended display driver (VDD1 & VDD2) would not work. A new extended display driver VDD3 is now installed. This issue has been resolved.

Fixed Issue – Artifacts at bottom of screen when sharing via Windows 10 (originated in v2.0.1.4) – Intermittently when sharing, the mirrored output will have image artifacts. This issue has been resolved.

Fixed Issue – Unit locks up when mirroring two or more devices (originated in v2.0.1.4)– Intermittently when mirroring two or more devices the unit would lock up. A power cycle would be required to use the unit again. This issue has been resolved.

Fixed Issue (originated in v2.0.1.4) – Expired Security Certificate issue when sharing content – The software certificate had expired and showed a warning when installing the application. This issue has been resolved.

 Worldwide Sales Offices

Anaheim • Raleigh • Silicon Valley • Dallas • Chicago • New York • Washington, DC • Toronto • Mexico City • Paris • London • Frankfurt
 Amersfoort • Moscow • Dubai • Johannesburg • New Delhi • Bangalore • Singapore • Seoul • Shanghai • Beijing • Tokyo

UNITED STATES

+800.633.9876
 Inside USA/Canada

+1.714.491.1500

EUROPE

+800.3987.6673
 Inside Europe

+31.33.453.4040

ASIA

+800.7339.8766
 Inside Asia

+65.6383.4400

MIDDLE EAST

+971.4.2991800



SOFTWARE RELEASE HISTORY

Released Version: 2.0.1.4**Affects:****Software Revision: 2.0.1.1****Date: April 27, 2018**

The following is a list of changes and fixes in this release.

Improved Feature - General housekeeping

Worldwide Sales Offices

Anaheim • Raleigh • Silicon Valley • Dallas • Chicago • New York • Washington, DC • Toronto • Mexico City • Paris • London • Frankfurt
Amersfoort • Moscow • Dubai • Johannesburg • New Delhi • Bangalore • Singapore • Seoul • Shanghai • Beijing • Tokyo

UNITED STATES

+800.633.9876
Inside USA/Canada

+1.714.491.1500

EUROPE

+800.3987.6673
Inside Europe

+31.33.453.4040

ASIA

+800.7339.8766
Inside Asia

+65.6383.4400

MIDDLE EAST

+971.4.2991800



SOFTWARE RELEASE HISTORY

Released Version: 2.0.1.1**Affects:****Software Revision: 2.0.0.8****Date: October 25, 2016**

The following is a list of changes and fixes in this release.

Added Support – AES-128 Encryption - Encryption from the ShareLink Windows software to the ShareLink is now supported.

Worldwide Sales Offices

Anaheim • Raleigh • Silicon Valley • Dallas • Chicago • New York • Washington, DC • Toronto • Mexico City • Paris • London • Frankfurt
Amersfoort • Moscow • Dubai • Johannesburg • New Delhi • Bangalore • Singapore • Seoul • Shanghai • Beijing • Tokyo

UNITED STATES

+800.633.9876
Inside USA/Canada

+1.714.491.1500

EUROPE

+800.3987.6673
Inside Europe

+31.33.453.4040

ASIA

+800.7339.8766
Inside Asia

+65.6383.4400

MIDDLE EAST

+971.4.2991800



SOFTWARE RELEASE HISTORY

Released Version: 2.0.0.8**Affects:****Software Revision: 2.0.0.2****Date: July 21, 2016**

The following is a list of changes and fixes in this release.

Added Support – Windows 10 is now officially supported

Worldwide Sales Offices

Anaheim • Raleigh • Silicon Valley • Dallas • Chicago • New York • Washington, DC • Toronto • Mexico City • Paris • London • Frankfurt
Amersfoort • Moscow • Dubai • Johannesburg • New Delhi • Bangalore • Singapore • Seoul • Shanghai • Beijing • Tokyo

UNITED STATES

+800.633.9876
Inside USA/Canada

+1.714.491.1500

EUROPE

+800.3987.6673
Inside Europe

+31.33.453.4040

ASIA

+800.7339.8766
Inside Asia

+65.6383.4400

MIDDLE EAST

+971.4.2991800



SOFTWARE RELEASE HISTORY

Released Version: 2.0.0.2

Affects:

Software Revision: 1.1.0.0

Date: November 10, 2015

The following is a list of changes and fixes in this release.

Improved Feature – General housekeeping.

Improved Feature – Choose Receiver window now displays hostname of the receiver, instead of the Wi-Fi name.

Worldwide Sales Offices

Anaheim • Raleigh • Silicon Valley • Dallas • Chicago • New York • Washington, DC • Toronto • Mexico City • Paris • London • Frankfurt
Amersfoort • Moscow • Dubai • Johannesburg • New Delhi • Bangalore • Singapore • Seoul • Shanghai • Beijing • Tokyo

UNITED STATES

+800.633.9876
Inside USA/Canada

+1.714.491.1500

EUROPE

+800.3987.6673
Inside Europe

+31.33.453.4040

ASIA

+800.7339.8766
Inside Asia

+65.6383.4400

MIDDLE EAST

+971.4.2991800



SOFTWARE RELEASE HISTORY

Released Version: 1.1.0.0**Affects:****Software Revision: 1.0.0.6****Date: February 5, 2015**

The following is a list of changes and fixes in this release.

Improved Feature – General housekeeping.

Worldwide Sales Offices

Anaheim • Raleigh • Silicon Valley • Dallas • Chicago • New York • Washington, DC • Toronto • Mexico City • Paris • London • Frankfurt
Amersfoort • Moscow • Dubai • Johannesburg • New Delhi • Bangalore • Singapore • Seoul • Shanghai • Beijing • Tokyo

UNITED STATES

+800.633.9876
Inside USA/Canada

+1.714.491.1500

EUROPE

+800.3987.6673
Inside Europe

+31.33.453.4040

ASIA

+800.7339.8766
Inside Asia

+65.6383.4400

MIDDLE EAST

+971.4.2991800



SOFTWARE RELEASE HISTORY

Released Version: 1.0.0.6**Affects:****Software Revision: 1.0.0.6****Date: January 21, 2015**

The following is a list of changes and fixes in this release.

Initial Release – This is the initial release of this software product.

Worldwide Sales Offices

Anaheim • Raleigh • Silicon Valley • Dallas • Chicago • New York • Washington, DC • Toronto • Mexico City • Paris • London • Frankfurt
Amersfoort • Moscow • Dubai • Johannesburg • New Delhi • Bangalore • Singapore • Seoul • Shanghai • Beijing • Tokyo

UNITED STATES

+800.633.9876
Inside USA/Canada

+1.714.491.1500

EUROPE

+800.3987.6673
Inside Europe

+31.33.453.4040

ASIA

+800.7339.8766
Inside Asia

+65.6383.4400

MIDDLE EAST

+971.4.2991800